

Clerk Report 08/10/25

1. SCC/AMEY HIGHWAYS REPORT UPDATES

Date Reported	No	Description	Status	Update	Amey Action
21/02/23	4310103	Green Lane, road speed, parking, accidents	Monitored	29/09/25	Bollards installed, no further works planned
23/02/23	4312520	Marchington Cliff, Unlit TS Damage/Missing/Worn		24/09/25	Work taken place, no further works planned
31/03/23	4318970	Silver Lane - blocked gully		27/06/23	Monitored under routine inspections
19/09/23	4343026	Church Lane - edge drop	Works carried out	29/09/23	Monitored under routine inspections
11/08/23	4338717	Church Lane - overgrown hedge blocking road sign	3rd party works	11/08/23	3rd party works being monitored
19/11/23	4351777	Moisty Lane - drain blocked	Unable to action	19/05/25	Work to be done when resources allow
26/01/24	4365252	Pothole, Windmill Drive	Ongoing	26/07/25	Work to be done when resources allow
26/01/24	4365130	Pothole on Hall Road	Ongoing	26/07/25	Work to be done when resources allow
19/02/24	4370679	Hall Road nr to Marchington Hall	Ongoing	19/09/25	Work to be done when resources allow
19/02/24	4370689	Hall Road nr to Marchington Hall	Ongoing	19/09/25	Work to be done when resources allow
19/02/24	4370693	Hall Road nr to The Poplars	Ongoing	19/09/25	Work to be done when resources allow
22/02/24	4371865	Bag Lane verges	Ongoing	22/08/25	Work to be done when resources allow
17/05/24	4389203	Top of Silver Lane ST14 8LL area around drain collapsing	resident reported	04/09/24	Monitored under routine inspections
23/05/24	4390407	Bag Lane - drain blocked by tarmac and red clay bank slippage	Reported	23/05/24	Addressed and being monitored
15/10/24	4410637	Woodroffe's Cliff - pothole	Cllr Lord reported	14/01/25	Addressed and being monitored
15/10/25	4410641	Highwood	Cllr Lord reported	27/01/25	Work to be done when resources allow
10/02/25	4428124	Marchington Cliff - potholes	Cllr Prince report	10/02/25	Marked up for attention
03/03/25	4431664	Marchington Cliff - blocked drain, gully	Cllr Prince report	03/03/25	Work to be done when resources allow
10/03/25	4432837	Gorsty Hill to Highwood - multiple potholes	Cllr Lord reported	24/07/25	Temporarily repaired 11/4/25
06/06/25	4443013	Brook bridge at Dog & Patridge - possible structural damage	Clerk report	04/07/25	Works raised to preserve and repair
09/06/25	4443371	B5017 Birch Cross, cobbles loose in road	Cllr Prince report	09/06/25	Report logged
04/07/25	4446160	Hound Hill - unstable trees encroaching onto Moreton Lane	Report via S Griffiths	04/07/25	Tree officer to inspect and take action
10/07/25	4446830	Moisty Lane - pothole	Cllr Morgan reported	23/07/25	Inspected, no defect found - continue to monitor
08/08/25	4449943	Marchington Cliff - pothole	Cllr Prince reported	08/08/25	Ongoing
08/08/25	4449941	Buttermilk Hill, Thorney Lanes - potholes	Cllr Prince reported	08/08/25	Ongoing

2. Footpath issues - to receive any items of concern

3. South Staffordshire Water - Asbestos mains concerns raised

4. Permissive Path Project